

February13, 2015

DearValuedCustomer,

In response to recent request

Pentax	Duodenoscope	ED-3430	QPC1679E	C1160E
Pentax	Duodenoscope	ED-3430K	QPC1679E	C1160E
Pentax	Duodenoscope	ED-3430T	QPC1679E	C1160E
Pentax	Duodenoscope	ED-3430TK	QPC1679E	C1160E
Pentax	Duodenoscope	ED-3440	QPC1679E	C1160E
Pentax	Duodenoscope	ED-3440T	QPC1679E	C1160E
Pentax	Duodenoscope	ED-3440TK	QPC1679E	C1160E
Pentax	Duodenoscope	ED-3270K	QPC1713E	C1160E
Pentax	Duodenoscope	ED-3280K	QPC1713E	C1160E
Pentax	Duodenoscope	ED-3470T	QPC1713E	C1160E
Pentax	Duodenoscope	ED-3470TK	QPC1713E	C1160E
Pentax	Duodenoscope	ED-3480TK	QPC1713E	C1160E
Pentax	Duodenoscope	ED-3485T	QPC1713E	C1160E
Pentax	Duodenoscope	ED-3490TK	QPC1713E	C1160E

Please note that if a Quick Connect tray is altered or damaged in any way, it ~~can~~ be used in the SYSTEM 1E and must be replaced. STERIS Corporation makes no claim of safety or liquid chemical sterilization efficacy when the Quick Connect SYSTEM 1E tray is altered, nor when these items are used with or